

CLIENT: DEMO CLIENT	INSPECTION TYPE: 1st Final Insp.
VENDOR: DEMO	RESULT: PASS
FACTORY: FACTORY	DATE OF INSPECTION: 8 giugno 2022
STYLE CODE: DEMO STYLE	STATUS : Itlay
STYLE NAME: PRODUCT DESCRIPTION	

NOTES: Please note that the repacking of inspected goods is done by the factory without TFS Holding inspector's supervision. Defects may appear after the inspection due to improper repacking, bad storage or transportation conditions and manufacturing process. The inspection scope is based on the specifications provided by our clients and it does not include product design validation; any consequence on the product quality found after the inspection & due to its design, such as durability of components, poor material etc., is not under TFS Holding's responsibility.

DISCLAIMER: The results reflect our findings at time and place of service and this report does not relieve sellers/manufacturers from their contractual liabilities & responsibilities or prejudice buyers' right for compensation for any apparent and/or hidden problems not detected during the service or occurring thereafter. The defects found by the inspector on the inspected samples were shown to the factory. The inspector advised the factory to repair/replace these samples. The inspected samples are randomly drawn from the total quantity available; some other defects may exist in the remaining goods that are not inspected.

FINAL REPORT: The report contains the findings of the inspection. The main information is summarized in the first page of the report. The detailed findings are reported in the other sections. In order to fully understand the inspection output and avoid missing important information we strongly advise you to read carefully the whole report.

IMPORTANT NOTICE: In case the Quantity check is failed, we strongly advise you to re-inspect your goods when all finished and available for inspection in your warehouse as some defects can appear in the remaining unchecked quantity or to call for a 2nd Inspection after 100% recheck by supplier.

In case the Workmanship check is failed or very close to the Acceptance Quality Limits we strongly advise you to liaise with your supplier to implement the necessary corrective actions and re-inspect your goods and to call for a 2nd Inspection after 100% recheck by supplier.

In case of Pending result you must give your acceptance or rejection of special instructions (extra tolerance, out of range approval, etc) and confirm to supplier if goods will be released or call for a 2nd Inspection after 100% recheck by supplier based on special instructions given.

LEGENDA:		Inspection Result:	
In Line Inspection	Inspection is performed during assembly process or with less than 80% of goods packed.	PASS	Defects found on Sample Size checked is less than the Acceptance Quality Limits
Pre-Final Inspection	Inspection is performed without some tools or mandatory documents (No sample or PPS, Final Packing list, Technical Sheet, etc)	FAIL	Defects found on Sample Size checked is greater than the Acceptance Quality Limits
1st Final Inspection	Inspection is performed with all tools and mandatory documents with 100% of goods packed (or less only with client approval)	PENDING	Defects found on Sample Size checked is less than the Acceptance Quality Limits but customer approval is required on some non-conformities found.
2nd & 3rd Final Inspection	Inspection is performed with all tools and mandatory documents with 100% of goods packed after 100% recheck by supplier following any special instructions given by client.	NO SHOW	No Inspection was performed because of not goods ready.

TFS HOLDING Spa Unipersonale - Stefan Karadja St. 7/B – 1000 – Sofia – Bulgaria - ID 204812990 - VAT BG 204812990 Tel (359) 2950 3053 www.tfsholding.eu

This document is confidential and is the sole property of TFS Holding SPA. It is to be used solely and exclusively by recipient. No part of this document may be reproduced or disseminated in any form or by any means (electronic, mechanical, photocopying, recording or otherwise) without the prior written consent of Textile

Fashion Solutions. No warranty is given in relation to any of the contents of this document. All rights reserved. © TFS Holding SPA Report Template BXJ12 All right reserved - 2018-2019

Style No.	DEMO STYLE			
Style Name	PRODUCT DESCRIPTION			
Material				
Color	-			
PO N°	Status	PO Qty	Pres. To QC	
AX12938	Itlay	999	999	
Qty x Colore -				
Packing % :	100,0%	1-3-5-33-55-77-88-		
N° of box checked				

Customer:	DEMO CLIENT
Vendor:	DEMO
C/O:	CHINA
Factory:	FACTORY
Destination:	Itlay
Line/Collection	SPRING SUMMER
Season:	2022
Inspection date:	8-giu-22
Delivery Date:	11-giu-22
Ship Mode :	Sea
Inspectors:	QC NAME

1st Final Insp.	
2	Apparel
FINAL INSPECTION RESULT	
PASS	
Report Language	English



MAIN INFO - POM - SIZES

Main Information	Notes	Point Of Measurement	Centimetri	Top	Size
Packing List	Available	CHEST 1/2	C		32
Technical File	Available	WAIST 1/2	C		33
Comments Chart	Available	BOTTOM	C		34
Approved Master	Available	SHOULDER	C		
App. swatches	Available	ARMHOLE	B		
App. trim card	Available	NECK WIDTH	B		

To Measure	MM	Insp. Lev.	AQL Level:	2.5	
Meas. Sample	32	2 - Level II	Sample Size:	80	
			Major allowed:	5	
Out of Toller.			Total Defects:	0	
				0	
DETAIL DEFECTS FOUND				0%	
				0%	
DEFECT	A	B	C	D	Total
CRITICAL	0	0	0	0	0
MAJOR	0	0	0	0	0
MINOR	0	0	0	0	0
COMMENT COMMENT COMMENT COMMENT COMMENT COMMENT COMMENT COMMENT COMMENT COMMENT COMMENT					

Packing Audit	Comments
Total Boxes in Packing List	20
Sample Size Boxes	5
Defects Found	0
Summary Conformity	Result
Visual	PASS
Workmanship	PASS
Measurement	PASS
Packing	PASS
Washing/Ironing	PASS
INSPECTION RESULT	
PASS	
TFS Quality Technician:	QC NAME
Report Validated By:	

PACKING INSPECTION

	Pack N°	Size	units	in box	Defect	#defect	Remarks
1	1	32	50	50			
2	3	33	50	50			
3	5	34	50	50			
4	33	34	50	50			
5							
6							
7							
8							
9							
10							
11							
12							
13							
14							
15							
16							
17							
18							
19							
20							
21							
22							
23							
24							
25							
26							
27							
28							

DEFECTS CLASSIFICATION

A	Leather - Material	CR	MJ	MN	B	Workmanship - Sewing - Assembly	CR	MJ	MN
A0	defect demo				B0				
A0					B0				
A0					B0				
A0					B0				
A0					B0				
C	Trims	CR	MJ	MN	D	Finishing - Packaging - Labelling	CR	MJ	MN
C0					D0				
C0					D0				
C0					D0				
C0					D0				
C0					D0				

Material

Color -

defect demo



Foto 1




Foto 2




Foto 3




Foto 4

TFS

Quality Covers

STANDARD PICTURES

<i>Small Photos</i>			
	Sample or PPS		
	Trims & Labelling & Barcode		
	Care Label		
	Wash Approved		
	Carton Box or Hanging		

<i>Big Photos</i>			
	Packing List		
	Measurement Chart		
	Carton Box or Hanging		
	Tecnical Sheet		
	Sample or PPS		


Material

Color -


Sample or PPS




Standard Pictures - Foto 1



Standard Pictures - Foto 2



Standard Pictures - Foto 3



Standard Pictures - Foto 4

Packing List



Standard Pictures - Foto 17

DOCUMENTS DETAILS

PO#	Colorway	Tot PO# Qty	Qty Presented	Balance/short shipment	To be Checked	TIMING DETAILS	
1	999	100		-100		1st QC Name:	
2	100	799		-799		2nd QC Name:	
3	555	100		-100		Arrival Time:	
						Waiting Time	
						Starting Time	
						Finishing Time	

1654

Additional Comments

ADDITIONAL COMMENT

PO Qty	Pres. To QC
999	999

**COMMENT COMMENT COMMENT
COMMENT COMMENT COMMENT
COMMENT COMMENT COMMENT
COMMENT**

To Measure	MM	Insp. Lev.	AQL Level:	2.5
Meas. Sample	32	2 - Level II	Sample Size:	80
			Major allowed:	5
Out of Toller.			Total Defects:	
			Defect %	

Packing % : 100%

List of box checked

1-3-5-33-55-77-88-